(M)

	Application No.	Applicant(s)	
ž	10/025,000	5,000 PARSONS ET AL.	
Notice of Allowability	Examiner	Art Unit	
	Omar Flores-Sánchez	3724	
The MAILING DATE of this communication appear All claims being allowable, PROSECUTION ON THE MERITS IS (herewith (or previously mailed), a Notice of Allowance (PTOL-85) NOTICE OF ALLOWABILITY IS NOT A GRANT OF PATENT RIGOT THE OFFICE OF THE OFFICE OF ALLOWABILITY IS NOT A GRANT OF PATENT RIGOT THE OFFICE OF THE OFFICE O	OR REMAINS) CLOSED in this apport or other appropriate communication GHTS. This application is subject to	plication. If not include will be mailed in due	ed course. THIS
1. This communication is responsive to 2/28/05.			
2. The allowed claim(s) is/are 1-14,16,18-29,31 and 32.			
3. The drawings filed on 12/27/04 are accepted by the Examiner.			
4.			
Attachment(s) 1. ☐ Notice of References Cited (PTO-892) 2. ☐ Notice of Draftperson's Patent Drawing Review (PTO-948) 3. ☐ Information Disclosure Statements (PTO-1449 or PTO/SB/08 Paper No./Mail Date	5. ☐ Notice of Informal Pa 6. ☐ Interview Summary Paper No./Mail Date 3), 7. ☑ Examiner's Amendman 8. ☑ Examiner's Stateme 9. ☐ Other	(PTO-413), e nent/Comment	·

1. An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Thomas R. Vigil on 07/25/05.

The application has been amended as follows:

In claim 25, "17" has been replaced by "14".

REASONS FOR ALLOWANCE

2. The following is an examiner's statement of reasons for allowance: Claims are allowable because Huang fails to teach a *connector pin* operatively *connecting* a first leg and a cutting blade and being slidably received in an elongated slot in a plate portion and the connector pin *causing movement* of the cutting blade as set forth in claims 1, 8 and 9.

Huang (5373639) teaches a cutting device, a plate portion 10 having top side, left and right sides and a slot 15, a transverse slit 12, a cutting blade 21, first and second legs 40, a shield portion 11, a cutting chamber 17, first and second legs are in an open position the cutting blade is in a retracted condition (see Fig. 3), first and second legs are moved into a closed position/fully closed position the blade is moved to the shield portion and a connecting/rolling element 26. However, Huang's rolling element 26 is *connected only* in the outer surface blade means 20 (see

Art Unit: 3724

col. 2, lines 9-11) in order to reducing the friction of the blade means inside head portion 10 and links members 30, 31 and 32 are the mechanism for *causing movement* of the cutting blade when the legs are moved to the closed position. Also, there is no motivation to replace Huang's rolling element for a pin because the function of the pin is to connect two parts, when the rolling element in this case is only for reducing the friction of the blade means inside head portion and the connection with the leg is performed by the links members.

Also, claims are allowable because Barrows (1066456) fails to teach a head member having a cutting chamber *between* a shield portion and a plate portion, when the shield portion having a cutting surface as set forth in claims 1, 8, 9, 14 and 26.

Barrows teaches a head member 1, a cutting chamber A1, a shield portion which is the area between a member A and a top end portion of the head member 1, a plate portion is the middle portion of the head member 1, a cutting surface which is the inside surface of the member A and transverse slit which is the space between the two head members 1 (see Fig. 3). However, Barrows's cutting chamber is located within the shield portion, instead of between the shield portion and the plate portion as set forth in claims 1, 8, 9, 14 and 26.

Claims are allowable because Barrows (1066456) fails to teach a first leg extension movable within a first leg and a second leg extension movable within a second leg.

Barrows teaches a head member 1, a cutting chamber A1, a shield portion which is the area between a member A and a top end portion of the head member 1, a first leg 7, a second leg 7, a cutting surface which is the inside surface of the member A and transverse slit which is the space between the two head members 1 (see Fig. 3). However, Barrows fails to teach a first leg

Application/Control Number: 10/025,000

Art Unit: 3724

extension movable within a first leg and a second leg extension movable within a second leg as

Page 4

set forth in claim 21.

Any comments considered necessary by applicant must be submitted no later than the

payment of the issue fee and, to avoid processing delays, should preferably accompany the issue

fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for

Allowance."

3. Any inquiry concerning this communication or earlier communications from the

examiner should be directed to Omar Flores-Sánchez whose telephone number is 571-272-4507.

The examiner can normally be reached on 8:00-5:00.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's

supervisor, Allan Shoap can be reached on 571-272-4514. The fax phone number for the

organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent

Application Information Retrieval (PAIR) system. Status information for published applications

may be obtained from either Private PAIR or Public PAIR. Status information for unpublished

applications is available through Private PAIR only. For more information about the PAIR

system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR

system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

ofs 7/31/05

Allan N. Shoap Supervisory Patent Examiner

Group 3700